RECORD OF SURVEY NO. 37-87

BEING A SURVEY OF THE CENTERLINE MONUMENTS AS ORIGINALLY SET PER PARADISE ESTATES UNITS 1, 2, AND 3 AS RECORDED IN MAP BOOK 6, PAGE 44, MAP BOOK 8, PAGE 32 AND TRACT MAP BOOK 9, PAGE 14 BEING LOCATED IN A PORTION OF THE SE 1/4 OF SECTION 30 AND IN A PORTION OF THE SW 1/4 OF THE SW 1/4 OF SECTION 29, TOWNSHIP 5 SOUTH, RANGE 31 EAST, MOUNT DIABLO MERIDIAN, COUNTY OF MONO, STATE OF CALIFORNIA

HISTORY OF SURVEYS

- R1: Record of Survey Map recorded on August 1, 1959 in Book 2 of Maps at Page 20.
- R2: Sierra Paradise Unit No. 1 Subdivision recorded on July 29, 1969 in Book 6 of Maps at Page 44.
- R3: Tract 37-2, Sierra Paradise Unit No. 2 Subdivision recorded on December 19, 1973 in Book 8 of Maps at Page 32.
- R4: Tract 37—17, Sierra Paradise Unit No. 3 Subdivision recorded on February 13, 1980 in Book 9 of Tract Maps at Page 14.

LEGEND

- Found corner as noted in CORNER DESCRIPTIONS hereon.
- Corner searched for and not found. Nothing set.
- Found a 2" inner diameter iron pipe and illegible tag set in concrete in pipe. Accepted as centerline monument per R2 or R3.
- Found a 2" inner diameter iron pipe and illegible tag set in concrete in pipe. Accepted as centerline monument per R4.
- Set 2"ø, aluminum cap with punch mark inscribed LS5149 on a 5/8"øx24" rebar.
- m Based on field measurements.
- (R*) Based on record information per HISTORY OF SURVEYS hereon.

CORNER DESCRIPTIONS

Found a 2-1/2'ø galvanized cap on a 2" inner diameter iron pipe.

Cap inscribed T5S

S30 NW1/4 CAA

30 NW1/4 CAA NE1/4 SE1/4 R31E

Cap up 0.5' w/ 4"x4"x18" high post inscribed USBM 1' northerly and carsonite marker inscribed Survey Marker 1' easterly from monument. Accepted for Basis of Bearings per R1.

- Found a 2" inner diameter iron pipe in a 3'ø rock mound. Pipe up 1.5'. Accepted for Basis of Bearings per R1.
- Found bent shank of spike (no shiner). Monument measured and found to be within acceptable survey tolerances. Accepted as centerline monument per R2, R3 or R4 as applicable.
- Found bent shank of spike (no shiner). Monument has been lowered to prevent removal by construction activity. Monument measured and found to be within acceptable survey tolerances. Accepted as centerline monument per R2, R3 or R4 as applicable.
- Found spike and illegible shiner. Monument has been lowered to prevent removal by construction activity. Monument measured and found to be within acceptable survey tolerances. Accepted as centerline monument per R2, R3 or R4 as applicable.
- Found spike and illegible shiner. Monument measured and found to be within acceptable survey tolerances. Accepted as centerline monument per R2, R3 or R4 as applicable.
- 6 Corner removed by construction operations. Corner reset by distance—distance measurement per R4.
- Found spike and illegible shiner. Monument measured and found to be not within acceptable survey tolerances. Monument not accepted

